BAKER TANK 6592

Department of Health Services Toxic Substances Control Division Sacramento, California

A	UNIFORM HAZARDOUS WASTE MANIFEST	1. Generato	rs US EPA D No. B b 6 1 0 0 0	Manifest Document No.	2. Pa	ື່ I is	not requ	the shaded areas ired by Federal			
	 Generator's Name and Mailing Address Generator's Phone (533–6677 	Douglas 190th &	Aircraft Co. Normandie , CA 90502		B. St	ate Manifest R 6 2 3 ate Generator 08651000	314	Number HQ-36-005698			
	5. Transporter 1 Company Name		6. US	EPA ID Number		ate Transport		カダブン/ /			
11	911 Process Co.		C A D 0 5 0	8 0 6 8 5 0	D. Tra	ansporter's Pl	none	/ 			
	7. Transporter 2 Company Name		8. US	EPAID Number		ate Transport ansporter's Pi		3 383-3863			
	 Designated Facility Name and Site Add O11 Process Co. 5756 Alba St. Los Angeles. CA 90058 	Iress	10. US CIAIDIO 5 0		<u>С</u> Н. Fa 2	ate Facility's AD050861 cility's Phone 13 585-	350				
	11. US DOT Description (Including Proper S	Shipping Name, Ha	zard Class, and II) Nur	nber) 12. Cont No.	ainers Type	13. Total Quantit	14. Unit Wt/Vol	I. Waste No.			
GENER	a Hazardous Waste Liquid	d nos-orm-e	NA9189	001	17	0466	20 G	221			
A T O R											
	0.										
	1.										
	Bio-Degradable Coolant Tramp 011 Water	35% 50%						15			
	15. Special Handling Instructions and Additional information Guide #31 Use gloves, goggles, respirator - If rejected, return to DAC										
	6. GENERATOR'S CERTIFICATION: I hereby proper shipping name and are classified according to applicable international an Unless I am a small quantity generate under Section 3002(b) of RCRA, I also have determined to be economically prinimizes the present and future threat Printed/Typed Name	d, packed, marked, nd national governa or who has been o certify that I hay practicable and I h	and labeled, and are in nent regulations. exempted by statute e a program in place ave selected the metr and the environment.	all respects in proper or or regulation from the to reduce the volume	duty to	on for transpoor o make a wa xicity of was	ort by highw ste minimiz te generate	zation certification of to the degree I able to me which			
	Donald C. Gerber		Sb Signature	1. W.H.	علم	• 4		Month Day Year			
E A Z S P	17. Transporter 1 Acknowledgement of Reprinted/Typed Name RODERTO RODER 18. Transporter 2 Acknowledgement of Re	Vesde.	Signature	to Plud.	d,	3843	2	Month Day Year			
ORTER	Printed/Typed Name		Signature					Month Day Year			
FACIL	19. Discrepancy Indication Space										
No.	20. Facility Owner or Operator: Certification	on of receipt of ha	zardous materials cov	ered by this manifest	evcent	se noted in	needla.				
_	Printed/Typed Name		Signature	0,000 0,0 1,0,0	90446	as joteu III	jtem is.	10 to 10			

DHS 8022 A (11/85) (EPA 8700—22)

86 234314

6% YELLOW: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS

se print or type. (Form designed for use o UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator	's US EPA ID No.	Manifest Document No.		is not		ne shaded area ed by Feder	
3. Generator's Name and Malling Address	Douglas 190th &	8 6 6 0 0 0 0 5 l _c Aircraft Co. Normandia	lodo lo lo		law. ate Manifest Docu 362343 ate Generator's ID	14		
4. Generator's Phone (5336677	Torrance	, CA 90502			086510005		Q-36-005(
5. Transporter 1 Company Name P11 Process Co.		6. US EPA ID I		. USS (GC 28) CO	ate Transporter's I ansporter's Phone	^D 70	873 <i>1</i>	
7. Transporter 2 Company Name		8. US EPAID	Number		ate Transporter's I		585-506	
Designated Facility Name and Site Add	ress	10. US EPA ID I	Number	. 27/20/6/20/00/00	ansporter's Phone ate Facility's ID			
011 Process Co. 5756 Alba St. Los Angeles, CA 90058	CIAIDIOISIOISIOISISISIOI			EAD05086850 H. Facility's Phone 213 585-5063				
11. US DOT Description (Including Proper S	hipping Name, Ha	zard Class, and ID Number)	12. Con No.	tainers Type	13. Total Quantity	14. Unit Wt/Vol	l. Waste No.	
a. Hazardous Waste Liquid	NOS- ORM-E	NA9189	001	TT	9 4690	G	221	
						-		
J. Additional Descriptions for Materials Lie	sted Above			K Ha	ndling Codes for \	Nastes Li	isted Above	
Bio-Degradable Coolant Tramp 011 Water	15% 35% 50%							
15. Special Handling Instructions and Addit Use gloves, goggles, r		Guide #31 If rejected, ret	urn to D	AC				
16. GENERATOR'S CERTIFICATION: I hereby proper shipping name and are classified according to applicable international an Unless I am a small quantity generate under Section 3002(b) of RCRA, I also have determined to be economically p minimizes the present and future threat	l, packed, marked, d national governm or who has been certify that I hav racticable and I h	and labeled, and are in all responent regulations. exempted by statute or regule a program in place to redulate averselected the method of and the environment.	pects in proper lation from the ce the volume	duty to	on for transport b o make a waste i xicity of waste o	y highwa minimizai enerated ly availat	tion certificati to the degre de to me wh	
Printed/Typed Name Donald C. Gerber		Signature Sb	W-H	ali			Aonth Day <u>Cl2 l f l f l</u>	
17. Transporter 1 Acknowledgement of Rec Printed/Typed Name	celpt of Materials	Signature			*** 29 ft == 200	ī	Month Day	
Roboetto P AND	CAde_	Austen	and.	رار	38432		فاللالا	
18. Transporter 2 Acknowledgement of Rec Printed/Typed Name	ceipt of Materials	Signature				,	donth Day	
19. Discrepancy Indication Space								
20. Facility Owner or Operator: Certification Printed/Typed Name	on of receipt of ha	zardous materials covered by Signature	this manifest	ехсер	t as noted in Iten	N. J. A.	Month Day	
						I	1111	
SELECTION OF A CONTRACT CONTRACT OF A CONTRA	AVVOIDES AND POST OF SERVICES OF SERVICES.	cors courte un orden (colle bases) l'édition avidable		S4449900000		8360 (PM 6788)	anar vallavel 200000000	